


Flame/Smoke Backflow Preventer, Open - E0200.10



The E0200.10 alarm appears on certain Rika stoves (Induo / Induo II) when the flame and/or smoke backflow preventer is not in the heating position.

Solution

1. Set the flame and/or smoke backflow preventer to the heating position
2. Acknowledge the error message

If the error reoccurs, a technician must be contacted.