


Open position sensor - E00010000.10



The E00010000.10 error code appears on Rika pellet inserts when the insert is not in the operating position.

Solution

Push the pellet insert into the correct position and secure it.